COMPLETION REPORT

1. Name of Work : **MAINTENANCE OF BOREWELL AT ABBIGERE & MEDARAHALLI IN WARD NO.12 IN SHETTYHALLI SUB DIVISION**

2. Sanctioned Estimate No. & Dt : EE/D.D/TS/144/14-15 - Dated:- 29/10/14

3. Head of Account which is Chargeable : P.1771 Zone Works - POW-Works

4. Work Order No. & Dt : EE/DD/No/241/2014-15 Dt: 24/01/15

5. Name of Contractor : **SRI.S.PRAKASH**

6a. Time stipulated for completion of work :

b. Delay in execution of work :

7. Measurement recorded in : M.B. No. 3416/14-15 Page No. 341501/341517/2

8. Check measurement of the Asst. : M.B. No. 3416/14-15 Page No. 341501/341517

Asst. Exe. Eng. / Exe. Eng :

9. Name of the Office / Official : ಕಿರಿಯ Assistant executive Engineer Shettihally Sub-Div

incharge of the work :

10. a) Asst. Engineer : Ravi. N.K.

b) Asst. Exe. Engineer : B.L. Jayalingappa

Sanctioned estimated amount	Amount claims as per actually vide as per bills	DIFFERENCE	
		Excess	Savings
20,00,000/-	19,99,201-50/-	—	109.5/-

1) Certified that the above work has been completed within the stipulated time noted in the work order.
2) Certified that the contractor has delayed and completed the work for which necessary fine has been recovered.
3) Certified that the above work has been executed by the contractor satisfactorily in accordance with the specification as embodied in the agreement.

Ravi. N.K. 30/11/15

ASST. ENGINEER

ASST. EXECUTIVE ENGINEER
SUB DIVISION
BRUHATH BANGALORE MAHANAGARA PALIKE

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ದಾಸರಹಳ್ಳಿ ವಲಯ, ಬೆಂಗಳೂರು-57

ACCOUNTS SUPTD. (**)**

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ